

ABON

Transmitter Name	Frequency [MHz]	Coding	Notes
T12018	40.685	Fixed Code	Not compatible with HL5.
T12030	40.685	Fixed Code	Not compatible with HL5.
1K AM HS	433.92	Rolling Code	
4K AM HS	433.92	Rolling Code	

Achenbach

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.35	Rolling Code	compatible since HomeLink Software Version 7

AET

Transmitter Name	Frequency [MHz]	Coding	Notes
TX 40	40.685	Fixed Code	Not compatible with HL5.

AKM

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.35	Rolling Code	

Allmatic

Transmitter Name	Frequency [MHz]	Coding	Notes
AKMY 1	30.875	Fixed Code	Not compatible with HL5.
AKMY 2	30.875	Fixed Code	Not compatible with HL5.
AKMY 4	30.875	Fixed Code	Not compatible with HL5.
AKMY 1	40.665	Fixed Code	Not compatible with HL5.
AKMY 2	40.665	Fixed Code	Not compatible with HL5.
AKMY 4	40.665	Fixed Code	Not compatible with HL5.
AEMX1	433.92	Fixed Code	
AEMX2	433.92	Fixed Code	

AEMX4	433.92	Fixed Code	
B.RO STAR	433.92	Rolling Code	
B.RO1WN	433.92	Rolling Code	
B.RO2WN	433.92	Rolling Code	
B.RO4WN	433.92	Rolling Code	
B.ROT12W	433.92	Rolling Code	
B.ROVER	433.92	Rolling Code	

Alltronik

Transmitter Name	Frequency [MHz]	Coding	Notes
S206	27.015	Fixed Code	Not compatible with HL5.
S215	27.015	Fixed Code	Not compatible with HL5.
S235	27.015	Fixed Code	Not compatible with HL5.
S 415	27.02	Fixed Code	Not compatible with HL5.
S406	40.685	Fixed Code	Not compatible with HL5.
S435-10	40.685	Fixed Code	Not compatible with HL5.
S435-40	40.685	Fixed Code	Not compatible with HL5.
S435B	40.685	Fixed Code	Not compatible with HL5.
S 415	40.69	Fixed Code	Not compatible with HL5.
S 406	433.91	Fixed Code	

ALUFORJA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

ALUKON

Transmitter Name	Frequency [MHz]	Coding	Notes
Comfort 220	868.3	Fixed Code	compatible since HomeLink Software Version 7
MT87A1-1	868.5	Fixed Code	compatible since HomeLink Software Version 7
MT87A1-2	868.5	Fixed Code	compatible since HomeLink Software Version 7
MT87A1-4	868.5	Fixed Code	compatible since HomeLink Software Version 7

ALULUX

Transmitter Name	Frequency [MHz]	Coding	Notes
------------------	-----------------	--------	-------

HS40A8	40.685	Fixed Code	Not compatible with HL5.
MT40A1 1-Kanal	40.685	Fixed Code	Not compatible with HL5.
MT40A1 2-Kanal	40.685	Fixed Code	Not compatible with HL5.
Digital 302	433.92	Fixed Code	
Digital 302	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 304	868.3	Fixed Code	compatible since HomeLink Software Version 7
MT87A1 1-Kanal	868.5	Fixed Code	compatible since HomeLink Software Version 7
MT87A1 2-Kanal	868.5	Fixed Code	compatible since HomeLink Software Version 7
MT87A1 4-Kanal	868.5	Fixed Code	compatible since HomeLink Software Version 7

Alutec

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Amboss

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.35	Rolling Code	compatible since HomeLink Software Version 7

Amsiko

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.35	Rolling Code	compatible since HomeLink Software Version 7

Angelmir

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.35	Rolling Code	compatible since HomeLink Software Version 7

Ansonic

Transmitter Name	Frequency [MHz]	Coding	Notes
SF40...	40.662	Fixed Code	Not compatible with HL5.
SA40...	40.685	Fixed Code	Not compatible with HL5.
SF433...	433.075	Fixed Code	compatible since HomeLink Software Version 7
SA434...	433.92	Fixed Code	
SA868...	868.35	Rolling Code	compatible since HomeLink Software Version 7

Antech Antriebstechnik

Transmitter Name	Frequency [MHz]	Coding	Notes
(BT40) 131500-10	40.685	Fixed Code	Not compatible with HL5.
(BT40) 131500-20	40.685	Fixed Code	Not compatible with HL5.
(BT40) 131500-30	40.685	Fixed Code	Not compatible with HL5.
4 Kanal 433,92 MHz 60030020	433.92	Rolling Code	
4 Kanal Multifrequenz 60030010	433.92 and 868.3	Rolling Code	

Aperto

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-27-5	27.045	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-434-2	434.42	Rolling Code	
TX03-434-4	434.42	Rolling Code	
TX03-434-4-XP	434.42	Rolling Code	
TX03-8-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
TX03-868-4-XP	868.8	Rolling Code	compatible since HomeLink Software Version 7

Aprimatic

Transmitter Name	Frequency [MHz]	Coding	Notes
TG2M	27.195	Fixed Code	Not compatible with HL5.
TG4M	27.195	Fixed Code	Not compatible with HL5.
-	30.895	Fixed Code	Not compatible with HL5.

Araujo

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

ATEC

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Atodor

Transmitter Name	Frequency [MHz]	Coding	Notes
G 750 EML	27.145	Fixed Code	Not compatible with HL5.
G4330E	433.92	Fixed Code	
G4332E	433.92	Fixed Code	
G4333E	433.92	Fixed Code	
G4335E	433.92	Fixed Code	

Attas / Dickert

Transmitter Name	Frequency [MHz]	Coding	Notes
HS DX27	27.015	Fixed Code	Not compatible with HL5.

Aufinger

Transmitter Name	Frequency [MHz]	Coding	Notes
2710N	27.015	Fixed Code	Not compatible with HL5.
4010N	40.685	Fixed Code	Not compatible with HL5.

433N	433.92	Fixed Code	compatible since HomeLink Software Version 7
434N	433.92	Fixed Code	

Autodoor

Transmitter Name	Frequency [MHz]	Coding	Notes
1A4443-2	27.045	Fixed Code	Not compatible with HL5.

AZIRA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

B&D

Transmitter Name	Frequency [MHz]	Coding	Notes
62170	433.92	Fixed Code	

BAME

Transmitter Name	Frequency [MHz]	Coding	Notes
Joy	433.92	Rolling Code	
JOY	433.92	Rolling Code	
King 2	433.92	Fixed Code	
Mizar	433.92	Fixed Code	

Bartelt

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

BBG

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Becker

Transmitter Name	Frequency [MHz]	Coding	Notes
1K	27.015	Fixed Code	Not compatible with HL5.
2K	27.015	Fixed Code	Not compatible with HL5.
3K	27.015	Fixed Code	Not compatible with HL5.
1K	40.685	Fixed Code	Not compatible with HL5.
1K Mini or Maxi	40.685	Fixed Code	Not compatible with HL5.
2K	40.685	Fixed Code	Not compatible with HL5.
3K	40.685	Fixed Code	Not compatible with HL5.
4K	40.685	Fixed Code	Not compatible with HL5.
4K Mini or Maxi	40.685	Fixed Code	Not compatible with HL5.

BelFox

Transmitter Name	Frequency [MHz]	Coding	Notes
7120	27.015	Fixed Code	Not compatible with HL5.

7121	27.015	Fixed Code	Not compatible with HL5.
7122	27.015	Fixed Code	Not compatible with HL5.
7123	27.015	Fixed Code	Not compatible with HL5.
7130	27.015	Fixed Code	Not compatible with HL5.
7131	27.015	Fixed Code	Not compatible with HL5.
7132	27.015	Fixed Code	Not compatible with HL5.
7133	27.015	Fixed Code	Not compatible with HL5.
7330	27.015	Fixed Code	Not compatible with HL5.
7331	27.015	Fixed Code	Not compatible with HL5.
7350	27.015	Fixed Code	Not compatible with HL5.
7120	40.685	Fixed Code	Not compatible with HL5.
7121	40.685	Fixed Code	Not compatible with HL5.
7122	40.685	Fixed Code	Not compatible with HL5.
7123	40.685	Fixed Code	Not compatible with HL5.
7230	40.685	Fixed Code	Not compatible with HL5.
7231	40.685	Fixed Code	Not compatible with HL5.
7232	40.685	Fixed Code	Not compatible with HL5.
7233	40.685	Fixed Code	Not compatible with HL5.
7430	40.685	Fixed Code	Not compatible with HL5.
7431	40.685	Fixed Code	Not compatible with HL5.
7450	40.685	Fixed Code	Not compatible with HL5.
7730	433.92	Fixed Code	
7731	433.92	Fixed Code	
7732	433.92	Fixed Code	
7733	433.92	Fixed Code	
7834	868.3	Fixed Code	compatible since HomeLink Software Version 7
7834-E	868.3	Fixed Code	compatible since HomeLink SW version 7
7834-E-2	868.3	Fixed Code	compatible since HomeLink SW version 7
7834-E-4	868.3	Fixed Code	compatible since HomeLink SW version 7
7834-E-M(att)	868.3	Fixed Code	compatible since HomeLink SW version 7
7834-mini	868.3	Fixed Code	compatible since HomeLink Software Version 7

BeluTec

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Beninca

Transmitter Name	Frequency [MHz]	Coding	Notes
LOT1E	30.875	Fixed Code	Not compatible with HL5.
LOT2E	30.875	Fixed Code	Not compatible with HL5.
LOT4E	30.875	Fixed Code	Not compatible with HL5.
LO.T2W	433.92	Fixed Code	
LO.T2WMR	433.92	Fixed Code	
LO.T2WMS	433.92	Fixed Code	
LO.T4W	433.92	Fixed Code	
ROLLKEY DELUXE	433.92	Rolling Code	compatible since HomeLink Software Version 7
ROLLKEY ELEGANT	433.92	Rolling Code	compatible since HomeLink Software Version 7
T2WK	433.92	Fixed Code	
T2WV	433.92	Rolling Code	compatible since HomeLink Software Version 7
T4WK	433.92	Fixed Code	
T4WV	433.92	Rolling Code	compatible since HomeLink Software Version 7

Berlemann

Transmitter Name	Frequency [MHz]	Coding	Notes
INOVA 27 4k	27.015	Fixed Code	Not compatible with HL5.compatible since HomeLink Software Version 7
INOVA 40 4k	40.685	Fixed Code	Not compatible with HL5.compatible since HomeLink Software Version 7
INOVA 433 2K	433.92	Fixed Code	compatible since HomeLink Software Version 7
INOVA 433 4k	433.92	Fixed Code	compatible since HomeLink Software Version 7
INOVA 434 1k	433.92	Fixed Code	compatible since HomeLink Software Version 7
INOVA 434 4k	433.92	Fixed Code	compatible since HomeLink Software Version 7

Bernal

Transmitter Name	Frequency [MHz]	Coding	Notes
SM-1	26.995	Fixed Code	Not compatible with HL5.
B1S27L	27	Fixed Code	Not compatible with HL5.
02 0001 00	27.015	Fixed Code	Not compatible with HL5.
BE27L	27.015	Fixed Code	Not compatible with HL5.
-	27.12	Fixed Code	Not compatible with HL5.
B1S40L	40.685	Fixed Code	Not compatible with HL5.
BE40L	40.685	Fixed Code	Not compatible with HL5.
B.RO1WN	433.92	Rolling Code	
B.RO2WN	433.92	Rolling Code	
B.RO4WN	433.92	Rolling Code	
RC1	433.92	Rolling Code	
MT87A2B / 2 Kanal	868.3	Rolling Code	compatible since HomeLink Software Version 7
MT87A2B / 4 Kanal	868.3	Rolling Code	compatible since HomeLink Software Version 7

Berner Torantriebe

Transmitter Name	Frequency [MHz]	Coding	Notes
SM1/SM1MD	26.995	Fixed Code	Not compatible with HL5.
SM2/SM2MD	26.995	Fixed Code	Not compatible with HL5.
SM4/SM4MD	26.995	Fixed Code	Not compatible with HL5.
B1S27L	27.015	Fixed Code	Not compatible with HL5.
B2S27L	27.015	Fixed Code	Not compatible with HL5.
B3S27L	27.015	Fixed Code	Not compatible with HL5.
B4S27L	27.015	Fixed Code	Not compatible with HL5.
BE 27 L	27.015	Fixed Code	Not compatible with HL5.
B140L	40.685	Fixed Code	Not compatible with HL5.
B1S40L	40.685	Fixed Code	Not compatible with HL5.
B240L	40.685	Fixed Code	Not compatible with HL5.
B2S40L	40.685	Fixed Code	Not compatible with HL5.
B3S40L	40.685	Fixed Code	Not compatible with HL5.
B440L	40.685	Fixed Code	Not compatible with HL5.
B4S40L	40.685	Fixed Code	Not compatible with HL5.
BE 40 L	40.685	Fixed Code	Not compatible with HL5.
RC1	433.92	Rolling Code	
RC2	433.92	Rolling Code	
RC4	433.92	Rolling Code	
SKX1MD	433.92	Fixed Code	
SKX2MD	433.92	Fixed Code	
SKX3MD	433.92	Fixed Code	

SKX4MD	433.92	Fixed Code	
RCBE868/4	868.36	Rolling Code	compatible since HomeLink Software Version 7

BFT

Transmitter Name	Frequency [MHz]	Coding	Notes
TEO-1	433.92	Fixed Code	
TEO-2	433.92	Fixed Code	
TEO-4	433.92	Fixed Code	

Big Tor

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Bistag

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

BKF

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Blasl

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Bosch

Transmitter Name	Frequency [MHz]	Coding	Notes
7 781 999 720	26.975	Fixed Code	Not compatible with HL5.
7 781 999 721	26.975	Fixed Code	Not compatible with HL5.
7 781 999 730	26.975	Fixed Code	Not compatible with HL5.
7 781 999 728	26.995	Fixed Code	Not compatible with HL5.

7 781 999 733	26.995	Fixed Code	Not compatible with HL5.
7 781 999 736	26.995	Fixed Code	Not compatible with HL5.
7 781 999 738	26.995	Fixed Code	Not compatible with HL5.
7 781 999 734	27.145	Fixed Code	Not compatible with HL5.
8 787 025 048	27.145	Fixed Code	Not compatible with HL5.
7 781 999 722	40.68	Fixed Code	Not compatible with HL5.
7 781 999 731	40.68	Fixed Code	Not compatible with HL5.
7 781 999 742	40.68	Fixed Code	Not compatible with HL5.
7 781 999 742	40.68	Fixed Code	Not compatible with HL5.
7 781 999 744	40.68	Fixed Code	Not compatible with HL5.
7 781 999 744	40.68	Fixed Code	Not compatible with HL5.
7 781 999 739	40.685	Fixed Code	Not compatible with HL5.

BRANKEMPER

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

BREDA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-434-4-XP	434.42	Rolling Code	

BRIOTUS

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Brix Zaun + Tor GmbH

Transmitter Name	Frequency [MHz]	Coding	Notes
TTE88042	40.685	Fixed Code	Not compatible with HL5.
TTE88043	40.685	Fixed Code	Not compatible with HL5.
TTE88044	40.685	Fixed Code	Not compatible with HL5.
TTE88052	433.92	Fixed Code	
TTE88054	433.92	Fixed Code	
TTE88120	868.3	Fixed Code	compatible since HomeLink Software Version 7
TTE88140	868.3	Fixed Code	compatible since HomeLink SW version 7

BURGERTORE

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Came

Transmitter Name	Frequency [MHz]	Coding	Notes
-	26.995	Fixed Code	Not compatible with HL5.
-	26.995	Fixed Code	Not compatible with HL5.
-	30.9	Fixed Code	Not compatible with HL5.
TOP 432M	433.92	Fixed Code	
TOP 432NA	433.92	Fixed Code	
TOP 432SA	433.92	Fixed Code	
TOP 434M	433.92	Fixed Code	
TOP 434MA	433.92	Fixed Code	
TOP 434NA	433.92	Fixed Code	
TOP432S	433.92	Fixed Code	

Cardale doors

Transmitter Name	Frequency [MHz]	Coding	Notes
433-1C	433.92	Fixed Code	
433-2C	433.92	Fixed Code	
433-4C	433.92	Fixed Code	
433-4C II	433.92	Fixed Code	
433-M1C	433.92	Fixed Code	
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7

Cardin

Transmitter Name	Frequency [MHz]	Coding	Notes
S 738	27.195	Fixed Code	Not compatible with HL5.
S 466 TX 2	29.875	Fixed Code	Not compatible with HL5.
S 466 TX 4	29.875	Fixed Code	Not compatible with HL5.
S 38 TX 2	30.875	Fixed Code	Not compatible with HL5.
S 38 TX4	30.875	Fixed Code	Not compatible with HL5.
S 48 TX 2	30.875	Fixed Code	Not compatible with HL5.
S 48 TX 4	30.875	Fixed Code	Not compatible with HL5.
S 476 TX 2	433.92	Fixed Code	
S 476 TX 4	433.92	Fixed Code	

Catnic

Transmitter Name	Frequency [MHz]	Coding	Notes
G 4180 E	418	Fixed Code	
G 4183 E	418	Fixed Code	

G 4330 E	433.92	Fixed Code	
G 4332 E	433.92	Fixed Code	
G 4333 E	433.92	Fixed Code	

Centurion deuren

Transmitter Name	Frequency [MHz]	Coding	Notes
433-1C	433.92	Fixed Code	
433-2C	433.92	Fixed Code	
433-4C	433.92	Fixed Code	
433-4C II	433.92	Fixed Code	
433-M1C	433.92	Fixed Code	
TX433-3C	433.92	Fixed Code	
TX433-4C	433.92	Fixed Code	
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-3C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7

Chamberlain

Transmitter Name	Frequency [MHz]	Coding	Notes
1A3231 1B	27.145	Fixed Code	Not compatible with HL5.
1A3232 1B	27.145	Fixed Code	Not compatible with HL5.
G 750 EML	27.145	Fixed Code	Not compatible with HL5.
G 751 EML	27.145	Fixed Code	Not compatible with HL5.
G 752 EML (2B)	27.145	Fixed Code	Not compatible with HL5.
G 754 EML (4B)	27.145	Fixed Code	Not compatible with HL5.
84335EML	433.92	Rolling Code	
G 4330 EML	433.92	Fixed Code	
G 4333 EML (3B)	433.92	Fixed Code	
G 4335 EML	433.92	Fixed Code	
G4330E	433.92	Fixed Code	
98685E	868.3	Rolling Code	compatible since HomeLink Software Version 7

Chamberlain Liftmaster

Transmitter Name	Frequency [MHz]	Coding	Notes
4182E	418	Fixed Code	
G 4180 EML	418	Fixed Code	

G 4183 EML (3B)	418	Fixed Code	
G 4185 EML	418	Fixed Code	
98685E	868.3	Rolling Code	compatible since HomeLink Software Version 7

Cierres Breogan

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Clem SA

Transmitter Name	Frequency [MHz]	Coding	Notes
Digicode MH-1	433.9	Fixed Code	

Coalval

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Corsaro

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Crawford

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-27-5	27.045	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
K 022475	433.92	Fixed Code	
K 022476	433.92	Fixed Code	
K 022477	433.92	Fixed Code	
T14637	433.92	Rolling Code	
T14638	433.92	Rolling Code	

Croci

Transmitter Name	Frequency [MHz]	Coding	Notes
RADIO.TX.2	433.92	Fixed Code	
TRASM 1	433.92	Fixed Code	
SF-TRASM	868.3	Fixed Code	compatible since HomeLink Software Version 7

CWI Electrotechnics

Transmitter Name	Frequency [MHz]	Coding	Notes
HE4331	433.92	Fixed Code	

Dandler

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Delma

Transmitter Name	Frequency [MHz]	Coding	Notes
Joy	433.92	Rolling Code	compatible since HomeLink Software Version 7
King 2	433.92	Fixed Code	
King 4	433.92	Fixed Code	

Dickert

Transmitter Name	Frequency [MHz]	Coding	Notes
AHS27...	27.015	Fixed Code	Not compatible with HL5.
DX27...	27.015	Fixed Code	Not compatible with HL5.
MAHS27...	27.015	Fixed Code	Not compatible with HL5.
AHS40...	40.685	Fixed Code	Not compatible with HL5.
DX40...	40.685	Fixed Code	Not compatible with HL5.
IAMS40	40.685	Fixed Code	Not compatible with HL5.
IFMS20	40.685	Fixed Code	Not compatible with HL5.
MAHS40...	40.685	Fixed Code	Not compatible with HL5.
IAMS-433...	433.92	Fixed Code	
IS-433...	433.92	Fixed Code	
MAHS433...	433.92	Fixed Code	
S10-433A...L...	433.92	Fixed Code	
S20-433A...L...	433.92	Fixed Code	
S5-433A...L...	433.92	Fixed Code	
HS868A...L...	868.3	Fixed Code	compatible since HomeLink Software Version 7
IS-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
S10-868A...L...	868.3	Fixed Code	compatible since HomeLink Software Version 7
S20-868A...L...	868.3	Fixed Code	compatible since HomeLink Software Version 7
S5-868A...L...	868.3	Fixed Code	compatible since HomeLink Software Version 7

Diplomat

Transmitter Name	Frequency [MHz]	Coding	Notes
433-1C	433.92	Fixed Code	
433-2C	433.92	Fixed Code	
433-4C	433.92	Fixed Code	
433-4C II	433.92	Fixed Code	
433-M1C	433.92	Fixed Code	
TX433-3C	433.92	Fixed Code	
TX433-4C	433.92	Fixed Code	

Diplomatdoerrar

Transmitter Name	Frequency [MHz]	Coding	Notes
433-1C	433.92	Fixed Code	
433-2C	433.92	Fixed Code	
433-4C	433.92	Fixed Code	
433-4C II	433.92	Fixed Code	
433-M1C	433.92	Fixed Code	
TX433-3C	433.92	Fixed Code	
TX433-4C	433.92	Fixed Code	
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7

Ditec

Transmitter Name	Frequency [MHz]	Coding	Notes
BIXAG4	40.685	Rolling Code	Not compatible with HL5.
BIXLG4	433.92	Rolling Code	
BIXLP2	433.92	Rolling Code	
BIXLS2	433.92	Rolling Code	

Domoferm

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

Doormaster

Transmitter Name	Frequency [MHz]	Coding	Notes
G750ED	27.145	Fixed Code	Not compatible with HL5.
G751ED	27.145	Fixed Code	Not compatible with HL5.
G4330ED	433.92	Fixed Code	

Dortech

Transmitter Name	Frequency [MHz]	Coding	Notes
Digital 101	27.045	Fixed Code	Not compatible with HL5.
Digital 211	433.92	Fixed Code	
Digital 212	433.92	Fixed Code	
Digital 214	433.92	Fixed Code	
Digital 302 / 64 173	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 304 / 64 037	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 313 / 64 180	868.3	Fixed Code	compatible since HomeLink Software Version 7

Droessler

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

E-King

Transmitter Name	Frequency [MHz]	Coding	Notes
433-1C	433.92	Fixed Code	
433-2C	433.92	Fixed Code	
433-4C	433.92	Fixed Code	
433-4C II	433.92	Fixed Code	
433-M1C	433.92	Fixed Code	
TX433-3C	433.92	Fixed Code	
TX433-4C	433.92	Fixed Code	
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-3C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7

easy-tec / door-tec

Transmitter Name	Frequency [MHz]	Coding	Notes
1 KHS DX27	27.015	Fixed Code	Not compatible with HL5.
2 KHS DX27	27.015	Fixed Code	Not compatible with HL5.
3 KHS DX27	27.015	Fixed Code	Not compatible with HL5.
4 KHS DX27	27.015	Fixed Code	Not compatible with HL5.
LW27/40BS4N	27.015	Fixed Code	Not compatible with HL5.
LW40 MS3/4	27.015	Fixed Code	Not compatible with HL5.
BIO	30.875	Fixed Code	Not compatible with HL5.
K	30.875	Fixed Code	Not compatible with HL5.
1 KHS DX40	40.685	Fixed Code	Not compatible with HL5.
1K FHS	40.685	Fixed Code	Not compatible with HL5.
1K FHS20	40.685	Fixed Code	Not compatible with HL5.
2 KHS DX40	40.685	Fixed Code	Not compatible with HL5.
3 KHS DX40	40.685	Fixed Code	Not compatible with HL5.
4 KHS DX40	40.685	Fixed Code	Not compatible with HL5.
40HS98K/U	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
40MIU/IK	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
40MS3/4	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
4K FHS	40.685	Fixed Code	Not compatible with HL5.
4K FHS20	40.685	Fixed Code	Not compatible with HL5.
MS4099U/K	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible

LW433HS98FU/FK	433.92	Fixed Code	
LW433MS2	433.92	Fixed Code	
NEO1	433.92	Rolling Code	
NEO2	433.92	Rolling Code	
NEO4	433.92	Rolling Code	
SKX2 ..	433.975	Fixed Code	
SKX3 ..	433.975	Fixed Code	
SKX4 ..	433.975	Fixed Code	

ECILA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

EcoStar

Transmitter Name	Frequency [MHz]	Coding	Notes
Ecostar 2	40.685	Fixed Code	Not compatible with HL5.
EcoStar4	40.685	Fixed Code	Not compatible with HL5.
RCT3b-433	433.92	Rolling Code	
RSC2-433	433.92	Rolling Code	
RSE2-433	433.92	Rolling Code	
RSZ1-433	433.92	Rolling Code	

Einhell

Transmitter Name	Frequency [MHz]	Coding	Notes
-	26.995	Fixed Code	Not compatible with HL5.
F1024/1	26.995	Fixed Code	Not compatible with HL5.
HS 434/6	434.07	Fixed Code	

Eisen-Fischer

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Eldat

Transmitter Name	Frequency [MHz]	Coding	Notes
FHS 06-1	433.92	Fixed Code	
FHS 06-2	433.92	Fixed Code	

FHS 06-4	433.92	Fixed Code	
FHS 20-3	433.92	Fixed Code	
FHS 20-4	433.92	Fixed Code	
FHS 21-1	433.92	Fixed Code	
FHS 21-2	433.92	Fixed Code	
RT20	868.3	Fixed Code	compatible since HomeLink Software Version 7
RT21	868.3	Fixed Code	compatible since HomeLink Software Version 7

Electrolift

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Elero

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-8-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Elka

Transmitter Name	Frequency [MHz]	Coding	Notes
SM 1	26.985	Fixed Code	Not compatible with HL5.
SKX 1LC	433.975	Fixed Code	
SK 1	434	Fixed Code	
SK 2	434	Fixed Code	
SK 3	434	Fixed Code	
SK 4	434	Fixed Code	
SKI 1	434	Fixed Code	
SKI 2	434	Fixed Code	
SKI 3	434	Fixed Code	
SKI 4	434	Fixed Code	

SKJ 2	434	Fixed Code	
SKX 1	434	Fixed Code	
SKX 2	434	Fixed Code	
SKX 3	434	Fixed Code	
SKX 4	434	Fixed Code	

Elletrab

Transmitter Name	Frequency [MHz]	Coding	Notes
-	433.92	Fixed Code	

ELOB

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Elso

Transmitter Name	Frequency [MHz]	Coding	Notes
RT 20	868.3	Fixed Code	compatible since HomeLink Software Version 7
RT 21	868.3	Fixed Code	compatible since HomeLink Software Version 7

Emutec

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

EOS

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Erreka

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
RES1 N09	433.92	Fixed Code	
RES2 N09	433.92	Fixed Code	

ES-Tore

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

Espace Della Vecchia

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

ETT 2 TRE

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Europe Doors

Transmitter Name	Frequency [MHz]	Coding	Notes
433-4C II	433.92	Fixed Code	compatible since HomeLink Software Version 7
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-3C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TX868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7
TXM868-2C	868.3	Fixed Code	compatible since HomeLink Software Version 7

Everest

Transmitter Name	Frequency [MHz]	Coding	Notes
------------------	-----------------	--------	-------

1K AM HS	433.92	Rolling Code	
4K AM HS	433.92	Rolling Code	

F.A.M.E.

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

FAAC

Transmitter Name	Frequency [MHz]	Coding	Notes
DH 02	26.975	Fixed Code	Not compatible with HL5.
DH 03	26.975	Fixed Code	Not compatible with HL5.
DH 04	26.975	Fixed Code	Not compatible with HL5.
27 DS	27	Fixed Code	Not compatible with HL5.
31 DS	30.875	Fixed Code	Not compatible with HL5.
EcoStar 2	40.685	Fixed Code	Not compatible with HL5.
EcoStar 4	40.685	Fixed Code	Not compatible with HL5.
FCT10	40.685	Fixed Code	Not compatible with HL5.
HS16	40.685	Fixed Code	Not compatible with HL5.
HS2	40.685	Fixed Code	Not compatible with HL5.
HS4	40.685	Fixed Code	Not compatible with HL5.
HSE2	40.685	Fixed Code	Not compatible with HL5.
HSM2	40.685	Fixed Code	Not compatible with HL5.
HSM4	40.685	Fixed Code	Not compatible with HL5.
TMN 40SL	40.685	Fixed Code	Not compatible with HL5.
418 SL	418	Fixed Code	
RS2	433.92	Fixed Code	
RS4	433.92	Fixed Code	
RSE2	433.92	Fixed Code	
RSM2	433.92	Fixed Code	
RSM4	433.92	Fixed Code	
TM1 433 DS	433.92	Fixed Code	
TM2 433 DS	433.92	Fixed Code	
TM2 433 ESL	433.92	Fixed Code	
TM3 433 DS	433.92	Fixed Code	
TM4 433 ESL	433.92	Fixed Code	

Falken-Tore

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Feig

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Feldmann

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

FINCHIUSURE

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-434-4-XP	434.42	Rolling Code	

France Fermeture

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Garador

Transmitter Name	Frequency [MHz]	Coding	Notes
DH 01	26.975	Fixed Code	Not compatible with HL5.
DH 02	26.975	Fixed Code	Not compatible with HL5.
DH 03	26.975	Fixed Code	Not compatible with HL5.
DH 04	26.975	Fixed Code	Not compatible with HL5.
EcoStar 2	40.685	Fixed Code	Not compatible with HL5.
EcoStar 4	40.685	Fixed Code	Not compatible with HL5.
FCT10	40.685	Fixed Code	Not compatible with HL5.
HS16	40.685	Fixed Code	Not compatible with HL5.
HS2	40.685	Fixed Code	Not compatible with HL5.
HS4	40.685	Fixed Code	Not compatible with HL5.
HSE2	40.685	Fixed Code	Not compatible with HL5.
HSM2	40.685	Fixed Code	Not compatible with HL5.
HSM4	40.685	Fixed Code	Not compatible with HL5.
RS2	433.92	Rolling Code	
RS4	433.92	Rolling Code	
RSE2	433.92	Rolling Code	
RSM2	433.92	Rolling Code	
RSM4	433.92	Rolling Code	

Garageportexperten

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Garog

Transmitter Name	Frequency [MHz]	Coding	Notes
S466	26.995	Fixed Code	Not compatible with HL5.

Gausemeier

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

GEBA

Transmitter Name	Frequency [MHz]	Coding	Notes
RCA T4SP 433	433.92	Fixed Code	

GFA-Elektromaten

Transmitter Name	Frequency [MHz]	Coding	Notes
M 512	26.985	Fixed Code	Not compatible with HL5.
K 512	433.92	Fixed Code	

GiBiDi

Transmitter Name	Frequency [MHz]	Coding	Notes
Arm AU01530	30.875	Fixed Code	Not compatible with HL5.
Arm AU01540	30.875	Fixed Code	Not compatible with HL5.
Open 70200	433.92	Fixed Code	
Open 70201	433.92	Fixed Code	
Roller AU01590	433.92	Rolling Code	compatible since HomeLink Software Version 7
Roller AU01600	433.92	Rolling Code	compatible since HomeLink Software Version 7
Roller AU01610	433.92	Rolling Code	compatible since HomeLink Software Version 7
Roller AU01680	433.92	Rolling Code	compatible since HomeLink Software Version 7
Roller AU01800	433.92	Rolling Code	compatible since HomeLink Software Version 7
Roller AU01810	433.92	Rolling Code	compatible since HomeLink Software Version 7

Gilgen Door Systems AG

Transmitter Name	Frequency [MHz]	Coding	Notes
BE40L	40.685	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
F7000-S2	433.92	Fixed Code	compatible since HomeLink Software Version 7
SFG2KG / Funk 9000 S2	868.3	Fixed Code	compatible since HomeLink Software Version 7
SFG4KG / Funk 9000 S4	868.3	Fixed Code	compatible since HomeLink Software Version 7
F9000 S4	868.45	Fixed Code	compatible since HomeLink Software Version 7

GFU 4	868.45	Fixed Code	compatible since HomeLink Software Version 7
-------	--------	------------	--

Gobbato

Transmitter Name	Frequency [MHz]	Coding	Notes
RAD/B1S	433.92	Fixed Code	
RAD/B2S	433.92	Fixed Code	
Tra2s	433.92	Rolling Code	compatible since HomeLink Software Version 7
Tra3s	433.92	Rolling Code	compatible since HomeLink Software Version 7

Goetzfried

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Groen + Jansen

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Groetz

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Guckelsberger Waldbrunn

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Guenther

Transmitter Name	Frequency [MHz]	Coding	Notes

T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Guttomat

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

GVK

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Gypass

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Hacker

Transmitter Name	Frequency [MHz]	Coding	Notes
27AM	26.995	Fixed Code	Not compatible with HL5.
40AM	40.685	Fixed Code	Not compatible with HL5.
40FM	40.685	Fixed Code	Not compatible with HL5.
SKR 433	433.92	Rolling Code	
SKRJ 433	433.92	Rolling Code	

Hees + Peters

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Heinzmann

Transmitter Name	Frequency [MHz]	Coding	Notes
657100	868.3	Fixed Code	compatible since HomeLink Software Version 7
657110	868.3	Fixed Code	compatible since HomeLink Software Version 7
657132	868.3	Fixed Code	compatible since HomeLink Software Version 7
656600	868.5	Rolling Code	compatible since HomeLink Software Version 7
656632	868.5	Rolling Code	compatible since HomeLink Software Version 7

Henderson

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-27-5	27.045	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-27-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
4K AM HS	433.92	Rolling Code	
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Heroal

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
Pocket 1/4	433.92	Rolling Code	compatible since HomeLink Software Version 7
Pocket-1K	433.92	Fixed Code	
Pocket-2K	433.92	Fixed Code	
Pocket-4K	433.92	Fixed Code	
S3-4	433.92	Fixed Code	
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Hild-Tortechnik

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

HL Torbau

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Hochtief

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

Hofbauer

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Holder

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Homentry

Transmitter Name	Frequency [MHz]	Coding	Notes
HE4331	433.92	Fixed Code	

Huth

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

HUTYRA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Hörmann

Transmitter Name	Frequency [MHz]	Coding	Notes
DH 01	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons

Compatible Device Manufacturers

DH 02	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
DH 03	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
DH 04	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
FCT10b-40	40.685	Fixed Code	Not compatible with HL5.
HS16-40	40.685	Fixed Code	Not compatible with HL5.
HS2-40	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
HS4-40	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
HSE2-40	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
HSM2-40	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
HSM4-40	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
S850	40.685	Fixed Code	Not compatible with HL5. Valid for transmitters with grey buttons
RCT3b-433	433.92	Rolling Code	
RS2-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RS4-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RSM2-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RSM4-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
FCT10b-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
FCT3b-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
FFL12-868	868.3	Fixed Code	compatible since HomeLink Software Version 7

Compatible Device Manufacturers

FIT2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HS1-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HS16-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HS2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HS4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSD2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSE2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSI-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSM2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSM4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSP4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSP4-C-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSZ1-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSZ2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7

Imexal

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Inova

Transmitter Name	Frequency [MHz]	Coding	Notes
INOVA 27 4k	27.015	Fixed Code	Not compatible with HL5.
INOVA 40 4k	40.685	Fixed Code	Not compatible with HL5.
INOVA 433 2K	433.92	Fixed Code	
INOVA 433 4k	433.92	Fixed Code	
INOVA 434 1k	433.92	Fixed Code	
INOVA 434 4k	433.92	Fixed Code	

Intertechno

Transmitter Name	Frequency [MHz]	Coding	Notes
YCT-99	433.92	Fixed Code	

ISEA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

JCM-tech

Transmitter Name	Frequency [MHz]	Coding	Notes
NEO1	433.92	Rolling Code	
NEO2	433.92	Rolling Code	
NEO4	433.92	Rolling Code	

JM

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

JP Weimann

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

JP. Bensheim

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

K-Plus

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

KACKER

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Kesting

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Key Automation

Transmitter Name	Frequency [MHz]	Coding	Notes
TXB-42	433.92	Fixed Code	
TXB-42R	433.92	Rolling Code	compatible since HomeLink Software Version 7
TXG-44	433.92	Fixed Code	
TXP-42	433.92	Fixed Code	
TXP-42N	433.92	Fixed Code	
TXP-42R	433.92	Rolling Code	compatible since HomeLink Software Version 7

Knies

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Koestner

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.

T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Komilfo I

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Kottmair & Hatef

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Kreiller

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

La Toulousaine

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Lakal

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

Lawiczak

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Layh

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

LEEB

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

LEPINARD

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Lift-Master

Transmitter Name	Frequency [MHz]	Coding	Notes
1A3531	27.145	Fixed Code	Not compatible with HL5.
750E	27.145	Fixed Code	Not compatible with HL5.
G3156	27.145	Fixed Code	Not compatible with HL5.
G3271E(1B)	27.145	Fixed Code	Not compatible with HL5.
G3272E	27.145	Fixed Code	Not compatible with HL5.
G750EML	27.145	Fixed Code	Not compatible with HL5.
G751EML	27.145	Fixed Code	Not compatible with HL5.
G752EML(2B)	27.145	Fixed Code	Not compatible with HL5.
G754EML(4B)	27.145	Fixed Code	Not compatible with HL5.
1A3570	40.685	Fixed Code	Not compatible with HL5.
G 4180 EML	418	Fixed Code	
G 4183 E	418	Fixed Code	
G 4185 E	418	Fixed Code	
94335E	433.92	Rolling Code	
G 4330 E	433.92	Fixed Code	
G 4332 E (2B)	433.92	Fixed Code	
G 4333 E (3B)	433.92	Fixed Code	
G 4335 E	433.92	Fixed Code	
98685E	868.3	Rolling Code	compatible since HomeLink Software Version 7

Lindpointner Torbau

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Marantec

Transmitter Name	Frequency [MHz]	Coding	Notes
Digital 101	27.045	Fixed Code	Not compatible with HL5.
Digital 211	433.92	Fixed Code	
Digital 212	433.92	Fixed Code	
Digital 214	433.92	Fixed Code	
Digital 302 / 64 176	433.92	Fixed Code	
Digital 304 / 64 133	433.92	Fixed Code	
Digital 313 / 64 183	433.92	Fixed Code	
Digital 313 / 76 955	433.92	Fixed Code	
Digital 302 / 64 173	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 304 / 64 037	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 313 / 64 180	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 313 / 76 852	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 304 / 67 522	868.6	Fixed Code	compatible since HomeLink Software Version 7
Digital 311 / 72 747	868.6	Fixed Code	compatible since HomeLink Software Version 7
Digital 314 / 72 748	868.6	Fixed Code	compatible since HomeLink Software Version 7

Matex Deuren

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Meier

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Meissner

Transmitter Name	Frequency [MHz]	Coding	Notes
Pocket-1/4	433.92	Fixed Code	

Memminger Torbau

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Menz-Holz

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Merlin

Transmitter Name	Frequency [MHz]	Coding	Notes
M872	27.145	Fixed Code	Not compatible with HL5.
M874	27.145	Fixed Code	Not compatible with HL5.
M802	40.685	Fixed Code	Not compatible with HL5.
M804	40.685	Fixed Code	Not compatible with HL5.
M832	433.92	Rolling Code	
M834	433.92	Rolling Code	
M842	433.92	Rolling Code	
M844	433.92	Rolling Code	

Mewald

Transmitter Name	Frequency [MHz]	Coding	Notes
G750E	27.145	Fixed Code	Not compatible with HL5.
G751E	27.145	Fixed Code	Not compatible with HL5.
G752E	27.145	Fixed Code	Not compatible with HL5.
G754E	27.145	Fixed Code	Not compatible with HL5.
G4330E	433.92	Fixed Code	

G4333E	433.92	Fixed Code	
G4335E	433.92	Fixed Code	

Mhouse

Transmitter Name	Frequency [MHz]	Coding	Notes
TX3	433.92	Rolling Code	compatible since HomeLink Software Version 7
TX4	433.92	Rolling Code	compatible since HomeLink Software Version 7

Mischler

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

MITHRA

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Mueller

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

MULTI CODE

Transmitter Name	Frequency [MHz]	Coding	Notes
3079-12	40.685	Fixed Code	Not compatible with HL5.

Multi Preve

Transmitter Name	Frequency [MHz]	Coding	Notes

TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
------------	-------	--------------	---

Nassau Door

Transmitter Name	Frequency [MHz]	Coding	Notes
26-12498	868.3	Fixed Code	compatible since HomeLink Software Version 7
26-12499	868.3	Fixed Code	compatible since HomeLink Software Version 7
26-12500	868.3	Fixed Code	compatible since HomeLink Software Version 7
26-12504	868.3	Fixed Code	compatible since HomeLink Software Version 7
26-12507	868.3	Fixed Code	compatible since HomeLink Software Version 7
26-12510	868.3	Fixed Code	compatible since HomeLink Software Version 7

Nice

Transmitter Name	Frequency [MHz]	Coding	Notes
EasyK K1	26.996	Fixed Code	Not compatible with HL5.
EasyK K1 M	26.996	Fixed Code	Not compatible with HL5.
EasyK K12M	26.996	Fixed Code	Not compatible with HL5.
EasyK K2	26.996	Fixed Code	Not compatible with HL5.
EasyK K2+2	26.996	Fixed Code	Not compatible with HL5.
EasyK K4	26.996	Fixed Code	Not compatible with HL5.
EasyK K4 M	26.996	Fixed Code	Not compatible with HL5.
Bio BT1K	30.875	Fixed Code	Not compatible with HL5.
Bio BT2K	30.875	Fixed Code	Not compatible with HL5.
Bio BT4K	30.875	Fixed Code	Not compatible with HL5.
EasyK K1	30.875	Fixed Code	Not compatible with HL5.
EasyK K1 M	30.875	Fixed Code	Not compatible with HL5.
EasyK K12M	30.875	Fixed Code	Not compatible with HL5.
EasyK K2	30.875	Fixed Code	Not compatible with HL5.
EasyK K2+2	30.875	Fixed Code	Not compatible with HL5.
EasyK K4	30.875	Fixed Code	Not compatible with HL5.
EasyK K4 M	30.875	Fixed Code	Not compatible with HL5.
Bio BT1K	40.685	Fixed Code	Not compatible with HL5.
Bio BT2K	40.685	Fixed Code	Not compatible with HL5.
Bio BT4K	40.685	Fixed Code	Not compatible with HL5.
EasyK K1	40.685	Fixed Code	Not compatible with HL5.
EasyK K1 M	40.685	Fixed Code	Not compatible with HL5.
EasyK K12M	40.685	Fixed Code	Not compatible with HL5.
EasyK K2	40.685	Fixed Code	Not compatible with HL5.
EasyK K2+2	40.685	Fixed Code	Not compatible with HL5.

EasyK K4	40.685	Fixed Code	Not compatible with HL5.
EasyK K4 M	40.685	Fixed Code	Not compatible with HL5.
Flo 1	433.92	Fixed Code	
Flo 2	433.92	Fixed Code	
Flo 4	433.92	Fixed Code	
Very VE	433.92	Fixed Code	

Niko

Transmitter Name	Frequency [MHz]	Coding	Notes
RT 20	868.3	Fixed Code	compatible since HomeLink Software Version 7
RT 21	868.3	Fixed Code	compatible since HomeLink Software Version 7

Normbau

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Normstahl/Entrematic

Transmitter Name	Frequency [MHz]	Coding	Notes
1K AM HS	433.92	Rolling Code	
4K AM HS	433.92	Rolling Code	
K086957	433.92	Rolling Code	
N000880-01-01	433.92	Rolling Code	
N002591-0002	433.92	Rolling Code	
N002592-00-01	433.92	Rolling Code	
T14429	433.92	Rolling Code	
T14435	433.92	Rolling Code	

Novoferm

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
HS 43-1E	433.92	Fixed Code	
Micro-Novotron 312	433.92	Rolling Code	
Micro-Novotron 512	433.92	Rolling Code	
Mini-Novotron 302	433.92	Rolling Code	
Mini-Novotron 304	433.92	Rolling Code	
Mini-Novotron 401	433.92	Fixed Code	

Mini-Novotron 404	433.92	Fixed Code	
Mini-Novotron 502	433.92	Rolling Code	
Mini-Novotron 504	433.92	Rolling Code	
Novotron 202 MB	433.92	Fixed Code	

Novotecnica

Transmitter Name	Frequency [MHz]	Coding	Notes
BIT E1	26.995	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT QET1	26.995	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT QET4	26.995	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT V1	30.9	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT V2	30.9	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT VT1	30.9	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIT VT4	30.9	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIX A1	40.685	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIX A2	40.685	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training
BIX A4	40.685	Fixed Code	Not compatible with HL5. Multiple button pushes necessary for training

NOW

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
------------	-------	--------------	---

Orther

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

PAMAX

Transmitter Name	Frequency [MHz]	Coding	Notes
SF 40-....	40.662	Fixed Code	Not compatible with HL5.
SF 40-....	40.662	Fixed Code	Not compatible with HL5.
SF 433-...	433.075	Fixed Code	
SF 433-...	433.075	Fixed Code	
SA 434-...	433.92	Rolling Code	
SA 434-...	433.92	Fixed Code	
SA 868-...	868.35	Rolling Code	compatible since HomeLink Software Version 7
SA 868-...	868.35	Rolling Code	compatible since HomeLink Software Version 7

Peha

Transmitter Name	Frequency [MHz]	Coding	Notes
RT 20	868.3	Fixed Code	compatible since HomeLink Software Version 7
RT 21	868.3	Fixed Code	compatible since HomeLink Software Version 7

Peters & Peters

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

PFT

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Pfullendorfer

Transmitter Name	Frequency [MHz]	Coding	Notes
SM1	26.995	Fixed Code	Not compatible with HL5.
SM1MD	26.995	Fixed Code	Not compatible with HL5.
SM2	26.995	Fixed Code	Not compatible with HL5.
SM2MD	26.995	Fixed Code	Not compatible with HL5.

SM3	26.995	Fixed Code	Not compatible with HL5.
SM3MD	26.995	Fixed Code	Not compatible with HL5.
SM4	26.995	Fixed Code	Not compatible with HL5.
SM4MD	26.995	Fixed Code	Not compatible with HL5.
-	433.92	Fixed Code	
Digital 211	433.92	Fixed Code	
Digital 302 / 64176	433.92	Fixed Code	
Digital 304 / 64133	433.92	Fixed Code	
SKX1MD	433.92	Fixed Code	
SKX2MD	433.92	Fixed Code	
SKX3MD	433.92	Fixed Code	
SKX4MD	433.92	Fixed Code	
SKJ	433.995	Fixed Code	
SKX3MD	433.995	Fixed Code	
SKX4MD	433.995	Fixed Code	
Digital 302 / 64173	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 304 / 64037	868.3	Fixed Code	compatible since HomeLink Software Version 7
Digital 313 / 64180	868.3	Fixed Code	compatible since HomeLink Software Version 7

Planzer

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Pleidelsheim

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Poellrath

Transmitter Name	Frequency [MHz]	Coding	Notes

TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
------------	-------	--------------	--

Portnorma

Transmitter Name	Frequency [MHz]	Coding	Notes
NEO1	433.92	Rolling Code	
NEO2	433.92	Rolling Code	
NEO4	433.92	Rolling Code	

Promotec

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Rademacher / Rator

Transmitter Name	Frequency [MHz]	Coding	Notes
27MHz	27.155	Fixed Code	Not compatible with HL5.
40MHz	40.685	Fixed Code	Not compatible with HL5.
4355	433.92	Rolling Code	
4385	433.92	Rolling Code	

Rasselstein

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Rauch

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

RCE

Transmitter Name	Frequency [MHz]	Coding	Notes
RBL1	30.875	Fixed Code	Not compatible with HL5.
RBL2	30.875	Fixed Code	Not compatible with HL5.
TK1	30.875	Fixed Code	Not compatible with HL5.
TK2	30.875	Fixed Code	Not compatible with HL5.
TK3	30.875	Fixed Code	Not compatible with HL5.
TK4	30.875	Fixed Code	Not compatible with HL5.
TP1	30.875	Fixed Code	Not compatible with HL5.
TP2	30.875	Fixed Code	Not compatible with HL5.

RDA

Transmitter Name	Frequency [MHz]	Coding	Notes
Combi 433	433.92	Fixed Code	
IND 01	433.92	Fixed Code	
IND 02	433.92	Fixed Code	
IND 04	433.92	Fixed Code	
TWINR	433.92	Rolling Code	
UGZ 433	433.92	Fixed Code	

Reichel

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Rekers

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Resch

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

RESPONSE

Transmitter Name	Frequency [MHz]	Coding	Notes
-	417.95	Fixed Code	

RIB

Transmitter Name	Frequency [MHz]	Coding	Notes
MOON 27	26.995	Fixed Code	Not compatible with HL5.
MOON 91	30.865	Fixed Code	Not compatible with HL5.
MOON 433	433.92	Fixed Code	

Riedl

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Rode

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

roma / Silento

Transmitter Name	Frequency [MHz]	Coding	Notes
Digital-211	433.92	Fixed Code	
Digital-212	433.92	Fixed Code	
Digital-214	433.92	Fixed Code	
Digital-221	433.92	Fixed Code	
Digital-222	433.92	Fixed Code	
Digital-224	433.92	Fixed Code	
Digital-231	433.92	Fixed Code	
MT87A1	868.5	Fixed Code	compatible since HomeLink Software Version 7
MT87A2	868.5	Fixed Code	compatible since HomeLink Software Version 7

RUKU

Transmitter Name	Frequency [MHz]	Coding	Notes
SF40...	40.662	Fixed Code	Not compatible with HL5.
SA40...	40.685	Fixed Code	Not compatible with HL5.
SA434...	433.92	Fixed Code	
SF433...	434.575	Fixed Code	compatible since HomeLink Software Version 7
SR 868-2	868.3	Fixed Code	compatible since HomeLink SW version 7
SR 868-4	868.3	Fixed Code	compatible since HomeLink SW version 7

SA868-1	868.35	Rolling Code	compatible since HomeLink Software Version 7
---------	--------	--------------	--

Rundum Meir

Transmitter Name	Frequency [MHz]	Coding	Notes
7121	27.015	Fixed Code	Not compatible with HL5.
7221	40.685	Fixed Code	Not compatible with HL5.
7520	433.92	Fixed Code	
87135	868.3	Fixed Code	compatible since HomeLink SW version 7

Ryterna

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Rötör Service

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Scarpatoni

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Schalk

Transmitter Name	Frequency [MHz]	Coding	Notes
FSH-4	433.92	Fixed Code	
FSH-8	433.92	Fixed Code	

Scharpf

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Schellenberg

Transmitter Name	Frequency [MHz]	Coding	Notes
Mizar / 21250	433.92	Fixed Code	

Schmoelling

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Schneider

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Schuetz

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Schwaben

Transmitter Name	Frequency [MHz]	Coding	Notes
-	40.685	Fixed Code	Not compatible with HL5.

Schweiger

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

SCOPE

Transmitter Name	Frequency [MHz]	Coding	Notes
-	418.01	Fixed Code	

seav

Transmitter Name	Frequency [MHz]	Coding	Notes
-	30.87	Fixed Code	Not compatible with HL5.
BeEasy TX	433.92	Fixed Code	
BeEasy TX Rolling Code	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy RH1	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy RH2	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy RH3	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy RS1	433.92	Rolling Code	compatible since HomeLink Software Version 7

BeHappy RS2	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy RS3	433.92	Rolling Code	compatible since HomeLink Software Version 7
BeHappy S1	433.92	Fixed Code	
BeHappy S2	433.92	Fixed Code	
BeHappy S3	433.92	Fixed Code	
TRS 1	433.92	Rolling Code	compatible since HomeLink Software Version 7
TRS 2	433.92	Rolling Code	compatible since HomeLink Software Version 7
TXS 1	433.92	Fixed Code	
TXS 2	433.92	Fixed Code	
TXS 3	433.92	Fixed Code	
TXS 4	433.92	Fixed Code	
TXS ESA	433.92	Fixed Code	
TXS ESA	433.92	Fixed Code	
TXS1	433.92	Fixed Code	
TXS2	433.92	Fixed Code	
TXS3	433.92	Fixed Code	

Sectic-Tec

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Seculux

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Seip

Transmitter Name	Frequency [MHz]	Coding	Notes
-	26.995	Fixed Code	Not compatible with HL5.
-	27.015	Fixed Code	Not compatible with HL5.
27 AM	27.015	Fixed Code	Not compatible with HL5.

-	40.685	Fixed Code	Not compatible with HL5.
-	40.685	Fixed Code	Not compatible with HL5.
40 AM	40.685	Fixed Code	Not compatible with HL5.
40 FM	40.685	Fixed Code	Not compatible with HL5.
-	433.92	Fixed Code	
433-12 AM	433.92	Fixed Code	
SKR 433	433.92	Rolling Code	
SKRJ433	433.92	Rolling Code	

Selve

Transmitter Name	Frequency [MHz]	Coding	Notes
297112	40.685	Fixed Code	Not compatible with HL5.
297113	40.685	Fixed Code	Not compatible with HL5.
297114	40.685	Fixed Code	Not compatible with HL5.
297121 Mini	40.685	Fixed Code	Not compatible with HL5.
297141	433.92	Fixed Code	
297142	433.92	Fixed Code	
297143	433.92	Fixed Code	
297145 Mini	433.92	Fixed Code	
297344	433.92	Fixed Code	

Serai

Transmitter Name	Frequency [MHz]	Coding	Notes
OG/52	433.92	Fixed Code	
OG/54	433.92	Fixed Code	

Sich Tel

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Siebau

Transmitter Name	Frequency [MHz]	Coding	Notes
MAX43-2	433.92	Rolling Code	
MAX43-4	433.92	Rolling Code	
MC43-2	433.92	Fixed Code	
MCHS43-2	433.92	Rolling Code	
MHS43-2	433.92	Rolling Code	
MHS43-4	433.92	Rolling Code	

MIX43-2	433.92	Rolling Code	
MS43-2	433.92	Fixed Code	
MS43-4	433.92	Fixed Code	
Multibit	433.92	Fixed Code	

Silento

Transmitter Name	Frequency [MHz]	Coding	Notes
Digital 211	433.92	Fixed Code	
Digital 212	433.92	Fixed Code	
Digital 214	433.92	Fixed Code	
Digital 221	433.92	Fixed Code	
Digital 222	433.92	Fixed Code	
Digital 224	433.92	Fixed Code	
Digital 231	433.92	Fixed Code	

Sistema

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

smd

Transmitter Name	Frequency [MHz]	Coding	Notes
LW27HS98	27.01	Fixed Code	Not compatible with HL5.
LW27/40BS4N	27.015	Fixed Code	Not compatible with HL5.
LW40 MS3/4	27.015	Fixed Code	Not compatible with HL5.
-	40.685	Fixed Code	Not compatible with HL5.
40HS98K/U	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
40MIU/IK	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
40MS3/4	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
LW40BSS4	40.685	Fixed Code	Not compatible with HL5.
MS4099U/K	40.685	Fixed Code	Not compatible with HL5.Red buttons are not compatible
-	433.92	Fixed Code	
LW433HS98FU/FK	433.92	Fixed Code	
LW433MIAU	433.92	Fixed Code	
LW433MS2	433.92	Fixed Code	

Sommer

Transmitter Name	Frequency [MHz]	Coding	Notes
S-435-B	27.015	Fixed Code	Not compatible with HL5.
T102497-27-5	27.045	Fixed Code	Not compatible with HL5.
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
S-435-40	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX02-434-2	434.42	Rolling Code	
TX03-434-4	434.42	Rolling Code	
TX03-434-4XP	434.42	Rolling Code	
TX03-868-4	868.3	Rolling Code	compatible since HomeLink Software Version 7
TX03-868-4-XP	868.3	Rolling Code	compatible since HomeLink Software Version 7
TX03-8-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Sonico

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.

Sonnleitner

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

SPPF

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

STA

Transmitter Name	Frequency [MHz]	Coding	Notes
------------------	-----------------	--------	-------

TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7
------------	-------	--------------	--

Stadelbauer

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Standoor

Transmitter Name	Frequency [MHz]	Coding	Notes
G 4330 E	433.92	Fixed Code	
G 4332 E	433.92	Fixed Code	
G 4333 E	433.92	Fixed Code	
G 4335 E	433.92	Fixed Code	

Stanley

Transmitter Name	Frequency [MHz]	Coding	Notes
1083-12	40.685	Fixed Code	Not compatible with HL5.

Steelline

Transmitter Name	Frequency [MHz]	Coding	Notes
868-4C	868.3	Fixed Code	compatible since HomeLink Software Version 7

Steinau

Transmitter Name	Frequency [MHz]	Coding	Notes
DH 01	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
DH 02	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
DH 03	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons
DH 04	26.975	Fixed Code	Not compatible with HL5. Valid for transmitters with green buttons

Compatible Device Manufacturers

FCT10b-40	40.685	Fixed Code	Not compatible with HL5.
HS16-40	40.685	Fixed Code	Not compatible with HL5.
HS2-40	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
HS4-40	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
HSE2-40	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
HSM2-40	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
HSM4-40	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
S850	40.685	Fixed Code	Not compatible with HL5.Valid for transmitters with grey buttons
RCT3b-433	433.92	Rolling Code	
RS2-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RS4-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RSM2-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
RSM4-433	433.92	Rolling Code	Valid for transmitters with yellow buttons
FCT10b-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
FCT3b-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
FFL12-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
FIT2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HS1-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HS16-868	868.3	Fixed Code	compatible since HomeLink Software Version 7

HS2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HS4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSD2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSE2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSI-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSM2-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSM4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSP4-868	868.3	Fixed Code	Valid for transmitters with blue buttons compatible since HomeLink Software Version 7
HSP4-C-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSZ1-868	868.3	Fixed Code	compatible since HomeLink Software Version 7
HSZ2-868	868.3	Fixed Code	compatible since HomeLink Software Version 7

Stock

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

SUPEERO

Transmitter Name	Frequency [MHz]	Coding	Notes
SM1	26.995	Fixed Code	Not compatible with HL5.
SM1DL	26.995	Fixed Code	Not compatible with HL5.
SM1MD	26.995	Fixed Code	Not compatible with HL5.
SM2	26.995	Fixed Code	Not compatible with HL5.
SM2DL	26.995	Fixed Code	Not compatible with HL5.
SM2MD	26.995	Fixed Code	Not compatible with HL5.
SM3	26.995	Fixed Code	Not compatible with HL5.
SM3DL	26.995	Fixed Code	Not compatible with HL5.
SM3MD	26.995	Fixed Code	Not compatible with HL5.
SM4	26.995	Fixed Code	Not compatible with HL5.
SM4DL	26.995	Fixed Code	Not compatible with HL5.
SM4MD	26.995	Fixed Code	Not compatible with HL5.
SKLC1	40.685	Fixed Code	Not compatible with HL5.
SKLC2	40.685	Fixed Code	Not compatible with HL5.
SKLC3	40.685	Fixed Code	Not compatible with HL5.
SKLC4	40.685	Fixed Code	Not compatible with HL5.
SKX1	433.995	Fixed Code	
SKX1DL	433.995	Fixed Code	
SKX1MD	433.995	Fixed Code	
SKX2	433.995	Fixed Code	
SKX22	433.995	Fixed Code	
SKX2DL	433.995	Fixed Code	
SKX2MD	433.995	Fixed Code	
SKX3	433.995	Fixed Code	
SKX33	433.995	Fixed Code	
SKX33DL	433.995	Fixed Code	
SKX3DL	433.995	Fixed Code	
SKX3MD	433.995	Fixed Code	
SKX4	433.995	Fixed Code	
SKX44	433.995	Fixed Code	
SKX44DL	433.995	Fixed Code	
SKX4DL	433.995	Fixed Code	
SKX4MD	433.995	Fixed Code	
SKX88	433.995	Fixed Code	
SKX88DL	433.995	Fixed Code	
SSKX4DL	433.995	Fixed Code	
SSKX4MD	433.995	Fixed Code	

T+T

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.

Teckentrup

Transmitter Name	Frequency [MHz]	Coding	Notes
Digital 212	433.92	Fixed Code	
Digital 214	433.92	Fixed Code	
FSH06	433.92	Fixed Code	
FSH07	433.92	Fixed Code	
Digital 302 / 69212	868.6	Fixed Code	
Digital 304 / 69213	868.6	Fixed Code	
Digital 313 / 69226	868.6	Fixed Code	

Tedsen

Transmitter Name	Frequency [MHz]	Coding	Notes
SM1..	26.995	Fixed Code	Not compatible with HL5.
SM2 ..	26.995	Fixed Code	Not compatible with HL5.
SM3 ..	26.995	Fixed Code	Not compatible with HL5.
SM4 ..	26.995	Fixed Code	Not compatible with HL5.
SKX 2 ..	433.92	Fixed Code	
SKX1 ..	433.92	Fixed Code	
SKX3 ..	433.92	Fixed Code	
SKX4 ..	433.92	Fixed Code	
SKX2 ..	433.975	Fixed Code	
SKX3 ..	433.975	Fixed Code	
SKX4 ..	433.975	Fixed Code	
SKJ	433.995	Fixed Code	
SKX1	433.995	Fixed Code	
SKX11MD	433.995	Fixed Code	
SKX1DL	433.995	Fixed Code	
SKX1HD	433.995	Fixed Code	
SKX1LC	433.995	Fixed Code	
SKX1MD	433.995	Fixed Code	
SKX1SL	433.995	Fixed Code	
SKX2	433.995	Fixed Code	

SKX22	433.995	Fixed Code	
SKX22MD	433.995	Fixed Code	
SKX2DL	433.995	Fixed Code	
SKX2HD	433.995	Fixed Code	
SKX2LC	433.995	Fixed Code	
SKX2MD	433.995	Fixed Code	
SKX2SL	433.995	Fixed Code	
SKX3	433.995	Fixed Code	
SKX33MD	433.995	Fixed Code	
SKX3DL	433.995	Fixed Code	
SKX3LC	433.995	Fixed Code	
SKX3MD	433.995	Fixed Code	
SKX3SL	433.995	Fixed Code	
SKX4	433.995	Fixed Code	
SKX42A,	433.995	Fixed Code	
SKX42B	433.995	Fixed Code	
SKX44MD	433.995	Fixed Code	
SKX4DL	433.995	Fixed Code	
SKX4HD	433.995	Fixed Code	
SKX4LC	433.995	Fixed Code	
SKX4MD	433.995	Fixed Code	
SKX4SL	433.995	Fixed Code	
SKX62	433.995	Fixed Code	
SKX6HD	433.995	Fixed Code	
SKX82	433.995	Fixed Code	
SKX88MD	433.995	Fixed Code	
SKX6HD	868.3	Fixed Code	compatible since HomeLink Software Version 7

Teleco

Transmitter Name	Frequency [MHz]	Coding	Notes
131500-10	40.685	Fixed Code	Not compatible with HL5.
131500-20	40.685	Fixed Code	Not compatible with HL5.
131500-30	40.685	Fixed Code	Not compatible with HL5.

Thress

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Turner

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Timmermann

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Tobias

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

TOR AG

Transmitter Name	Frequency [MHz]	Coding	Notes
S206 (1 Kanal / 1 channel)	27.015	Fixed Code	Not compatible with HL5.
S206 (2 Kanal / 2 channel)	27.015	Fixed Code	Not compatible with HL5.
S206 (4 Kanal / 4 channel)	27.015	Fixed Code	Not compatible with HL5.
S215 (1 Kanal / 1 channel)	27.015	Fixed Code	Not compatible with HL5.
S215 (2 Kanal / 2 channel)	27.015	Fixed Code	Not compatible with HL5.
S235	27.015	Fixed Code	Not compatible with HL5.
S406 (1 Kanal / 1 channel)	40.685	Fixed Code	Not compatible with HL5.
S406 (2 Kanal / 2 channel)	40.685	Fixed Code	Not compatible with HL5.
S406 (4 Kanal / 4 channel)	40.685	Fixed Code	Not compatible with HL5.

S415 (1 Kanal / 1 channel)	40.685	Fixed Code	Not compatible with HL5.
S415 (2 Kanal / 2 channel)	40.685	Fixed Code	Not compatible with HL5.
S435	40.685	Fixed Code	Not compatible with HL5.
TX 41	40.685	Fixed Code	Not compatible with HL5.
93121500	433.9	Fixed Code	
TX 43	433.92	Fixed Code	

Torbau Kraemer

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Torbau Pleidelsheim

Transmitter Name	Frequency [MHz]	Coding	Notes
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Torbau Schwaben

Transmitter Name	Frequency [MHz]	Coding	Notes
SM1	26.995	Fixed Code	Not compatible with HL5.
SM2	26.995	Fixed Code	Not compatible with HL5.
SM3	26.995	Fixed Code	Not compatible with HL5.
SM4	26.995	Fixed Code	Not compatible with HL5.
BE40L	40.685	Fixed Code	Not compatible with HL5.
HS2	40.685	Fixed Code	Not compatible with HL5.
HS4	40.685	Fixed Code	Not compatible with HL5.
SMX1	433.92	Fixed Code	
SMX2	433.92	Fixed Code	
SMX3	433.92	Fixed Code	
SMX4	433.92	Fixed Code	

TorKomfort / ToKo

Transmitter Name	Frequency [MHz]	Coding	Notes
27AM	26.995	Fixed Code	Not compatible with HL5.
40AM	40.685	Fixed Code	Not compatible with HL5.

40FM	40.685	Fixed Code	Not compatible with HL5.
SKR433	433.92	Rolling Code	
SKRJ433	433.92	Rolling Code	

Tormatic

Transmitter Name	Frequency [MHz]	Coding	Notes
MAX 43-2	433.92	Rolling Code	
MAX 43-4	433.92	Rolling Code	
MC43-2	433.92	Fixed Code	
MCHS 43-2	433.92	Rolling Code	
MHS 43-2	433.92	Rolling Code	
MHS 43-4	433.92	Rolling Code	
MIX43-2	433.92	Rolling Code	
MS43-2	433.92	Fixed Code	
MSC43-4	433.92	Fixed Code	
Multibit (1 Kanal / 1 channel)	433.92	Fixed Code	
Multibit (4 Kanal / 4 channel)	433.92	Fixed Code	
TX 43	433.92	Fixed Code	

Tormax

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Torprimus

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868	Rolling Code	

Tousek

Transmitter Name	Frequency [MHz]	Coding	Notes
(BT40) 131500-10	40.685	Fixed Code	Not compatible with HL5.
(BT40) 131500-20	40.685	Fixed Code	Not compatible with HL5.
(BT40) 131500-30	40.685	Fixed Code	Not compatible with HL5.
RS 433 TXR-1 13160010	433.92	Rolling Code	
RS 433 TXR-2 13160020	433.92	Rolling Code	
RS 433 TXR-2B 13160200	433.92	Rolling Code	

RS 433 TXR-4 13160030	433.92	Rolling Code	
RS 433 TXR-4B 13160210	433.92	Rolling Code	
RS 868 TXR-1 13180010	868.3	Rolling Code	compatible since HomeLink SW version 7
RS 868 TXR-2 13180020	868.3	Rolling Code	compatible since HomeLink SW version 7
RS 868 TXR-2B 13180050	868.3	Rolling Code	compatible since HomeLink SW version 7
RS 868 TXR-4 13180030	868.3	Rolling Code	compatible since HomeLink SW version 7
RS 868 TXR-4B 13180060	868.3	Rolling Code	compatible since HomeLink SW version 7

Traders

Transmitter Name	Frequency [MHz]	Coding	Notes
-	27.015	Fixed Code	Not compatible with HL5.
1K FM HS FHS	40.685	Fixed Code	Not compatible with HL5.
G4330E	433.92	Fixed Code	
G4332E	433.92	Fixed Code	
G4333E	433.92	Fixed Code	
G4335E	433.92	Fixed Code	

Trido

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Triebenbacher

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Tubauto

Transmitter Name	Frequency [MHz]	Coding	Notes
DH 01	26.975	Fixed Code	Not compatible with HL5.
DH 02	26.975	Fixed Code	Not compatible with HL5.
DH 03	26.975	Fixed Code	Not compatible with HL5.
DH 04	26.975	Fixed Code	Not compatible with HL5.

Compatible Device Manufacturers

EcoStar 2	40.685	Fixed Code	Not compatible with HL5.
EcoStar 4	40.685	Fixed Code	Not compatible with HL5.
FCT10	40.685	Fixed Code	Not compatible with HL5.
HS16	40.685	Fixed Code	Not compatible with HL5.
HS2	40.685	Fixed Code	Not compatible with HL5.
HS4	40.685	Fixed Code	Not compatible with HL5.
HSE2	40.685	Fixed Code	Not compatible with HL5.
HSM2	40.685	Fixed Code	Not compatible with HL5.
HSM4	40.685	Fixed Code	Not compatible with HL5.
RS2	433.92	Fixed Code	
RS4	433.92	Fixed Code	
RSE2	433.92	Fixed Code	
RSM2	433.92	Fixed Code	
RSM4	433.92	Fixed Code	

UNINORM

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Universal

Transmitter Name	Frequency [MHz]	Coding	Notes
-	433.92	Fixed Code	

V2

Transmitter Name	Frequency [MHz]	Coding	Notes
TSC2	433.92	Fixed Code	
TSC4	433.92	Fixed Code	
TSR2	433.92	Fixed Code	
TSR4	433.92	Fixed Code	

Valnes

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Vanhalme

Transmitter Name	Frequency [MHz]	Coding	Notes
MAC B 401	40.685	Fixed Code	Not compatible with HL5.
MAC B 402	40.685	Fixed Code	Not compatible with HL5.
MAC B 404	40.685	Fixed Code	Not compatible with HL5.

Vendôme

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Weller

Transmitter Name	Frequency [MHz]	Coding	Notes
MT40A2_1	40.685	Fixed Code	Not compatible with HL5.
MT40A2_2	40.685	Fixed Code	Not compatible with HL5.
MT40A2_4	40.685	Fixed Code	Not compatible with HL5.
MT87A1	868.5	Rolling Code	compatible since HomeLink Software Version 7
MT87A2	868.5	Rolling Code	compatible since HomeLink Software Version 7

WERMELINGER

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

WESSEX

Transmitter Name	Frequency [MHz]	Coding	Notes
-	417.98	Fixed Code	

WI?NIOWSKI

Transmitter Name	Frequency [MHz]	Coding	Notes
2A433	433.92	Rolling Code	
2k433	433.92	Rolling Code	
4A433	433.92	Rolling Code	
4GO	433.92	Rolling Code	
4k433	433.92	Rolling Code	
COVER	433.92	Rolling Code	

Wickes

Transmitter Name	Frequency [MHz]	Coding	Notes
-	417.96	Fixed Code	
200087	433.92	Fixed Code	
G 4335 E	433.92	Fixed Code	

Woelm

Transmitter Name	Frequency [MHz]	Coding	Notes

1110009141	27.015	Fixed Code	Not compatible with HL5.
1110009142	27.015	Fixed Code	Not compatible with HL5.
1110009143	868.3	Fixed Code	compatible since HomeLink Software Version 7
1110009144	868.3	Fixed Code	compatible since HomeLink Software Version 7

Wotan

Transmitter Name	Frequency [MHz]	Coding	Notes
11	27.145	Fixed Code	Not compatible with HL5.
G750E	27.145	Fixed Code	Not compatible with HL5.
G752E	27.145	Fixed Code	Not compatible with HL5.
G754E	27.145	Fixed Code	Not compatible with HL5.
11-1B	433.92	Fixed Code	
11-2B	433.92	Fixed Code	
11-3B	433.92	Fixed Code	
G4330E	433.92	Fixed Code	
G4333E	433.92	Fixed Code	
G4335E	433.92	Fixed Code	

WURM

Transmitter Name	Frequency [MHz]	Coding	Notes
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7

Zweygart

Transmitter Name	Frequency [MHz]	Coding	Notes
RFKCO-40-5	40.685	Fixed Code	Not compatible with HL5.
T102497-40-5	40.685	Fixed Code	Not compatible with HL5.
T397-40-2	40.685	Fixed Code	Not compatible with HL5.
TX02-40-2	40.685	Fixed Code	Not compatible with HL5.
TX03-40-1/5	40.685	Fixed Code	Not compatible with HL5.
TX04-40-15	40.685	Fixed Code	Not compatible with HL5.
TX03-868-4	868.8	Rolling Code	compatible since HomeLink Software Version 7